


WHICH WOULD YOU PREFER?

One half inch of scale formation can increase your energy cost by 70%!



PICTURED BELOW are the inlet and outlet of a HALO 5 after 7 years in service.



Industry leading 25-year warranty with PARTS & LABOR on the 1st 10-years!



Pictured above left:

After nearly 7 years on the San Diego municipal water with no water treatment installed, this water heater was destroyed by the accumulation of scale and corrosion.

Pictured above right:

After nearly 7 years on San Diego municipal water with the HALO 5 Whole House Filtration and Conditioning system installed, there is NO evidence of scale or corrosion.